

Appearance: pigmented liquid

Odour: mild glycol ether

SECTION 4 - Fire and Explosion Hazard Data

Flash Point (deg C) and Method: 49

Flammable Limits/% Volume in Air: LEL:1.26 @ 69°C UEL:15.8 @ 127°C

Autoignition Temperature (deg C): 235

Extinguishing Media: Carbon Dioxide,Water Fog,Dry Chemical,Foam

Special Fire Fighting Procedures: Wear Self-contained Breathing Apparatus and approved protective clothing use water spray to keep container cool.

Ignitable: YES: NO:X

Unusual Fire and Explosion Hazards: May form peroxides of unknown stability.

SECTION 5 - Reactivity Data

Stable: x Hazardous Polymerization:Will Not Occur
at ambient temperature, above 145°C may cause slow oxidation decomposition.

Incompatibility (Materials to Avoid):Oxidizing Agents

Conditions of Reactivity/Instability:Excessive heat,sparks and open flames
in the presence of oxidizing material

Hazardous Decomposition or Byproducts:Oxides of carbon(co,co2), aldehydes,
acids and other organic compounds may be formed during combustion.

SECTION 6 - Health Hazard Data

Primary Routes Of Exposure:

Inhalation:Nose and throat irritant Skin Contact:Irritant

Skin Absorbtion:Repeated contact may cause dermatitis in sensitive
individuals

Ingestion:May cause headache,nausea,vomiting and possible blood toxic.

Eye Contact:Irritant, may cause corneal damage.

Health Hazards:

Acute: May cause eye and skin irritation, and sensitization

Chronic: None Known

SECTION 7 - First Aid Measures

EMERGENCY AND FIRST AID PROCEDURES:

Inhalation: Move to fresh air. Give oxygen if breathing is difficult

Ingestion: Do not induce vomiting. Obtain medical attention immediately

Eyes: Flush eyes with water for at least 15 minutes

Skin: Wash with mild soap and water

SECTION 8 - Control Measures

Respiratory Protection: Use NIOSH approved respirator for organic vapours.

Ventilation: Local and mechanical exhaust are recommended to minimize exposure

Protective Gloves: Impervious gloves should be worn when handling this material

Eye Protection: Splash proof chemical goggles

Other Protective Clothing/Material/Equipment: Barrier Cream

Work/Hygienic Practices: Wash thoroughly after handling

SECTION 9 - Precautions for Safe Handling and Use

Waste Disposal Method: In accordance with all Federal, Provincial,
State and Local regulations

Handling and Storage: Store in a cool, dry, well ventilated area,
away from heat and ignition sources

Spill and Leak Procedure: Avoid all personal contact. Take up with
absorbent material. Flush area with water

Other Precautions: Avoid contact with eyes, skin or clothing.
Avoid breathing vapour, mist or spray

THE INFORMATION CONTAINED IN THIS FORM IS BASED ON DATA FROM SOURCES
CONSIDERED TO BE RELIABLE BUT NIAGARA PROTECTIVE COATINGS DOES NOT GUARANTEE
THE ACCURACY OR COMPLETENESS THEREOF. THE INFORMATION IS PROVIDED AS A SERVICE
TO PERSONS PURCHASING OR USING THE MATERIAL TO WHICH IT REFERS AND NIAGARA
PROTECTIVE COATINGS EXPRESSLY DISCLAIMS ALL LIABILITY FOR LOSS OR DAMAGE,
INCLUDING CONSEQUENTIAL LOSS, OR FOR INJURY TO PERSONS (INCLUDING DEATH)
ARISING DIRECTLY OR INDIRECTLY FROM RELIANCE UPON THE INFORMATION OR USE OF
THE MATERIAL.